



American Way Manufacturing, Inc.

Components for Building Excellence

FIELD CUT STAIR BRACKET INSTRUCTIONS

- 1.) Determine angle of stair.
- 2.) Measure between posts for rail lengths.
- 3.) Slide "T" bracket or SR 24V bracket over rail, mark the angle and cut.
- 4.) Bracket includes 2 -3" stainless steel screws.

